



AFRICAN EXPERTS



MULTI-DISCIPLINARY



INTERNATIONAL FOOTPRINT



Client: DMC Rietkuil Coal Mine
Services: Stormwater Management Report
Appointment Date: August 2011

Delta Mining Consolidated, South Africa

Stormwater Management Report

Location

The mine is approximately 12km east of Delmas in the Mpumalanga Province and close to the surfaced R50 (Provincial) road.



Stormwater Management

- Dirty & clean stormwater catchments.
- Impacts on the existing groundwater resources.
- Prevention of the erosion of the exiting water courses.
- Mitigation of flooding to neighbouring properties in the mining areas due to the proposed mine footprint & mining.

Nurizon South Africa
T: +27 (0)12 345 3649
E: info@nurizon.co.za
W: www.nurizonconsulting.com

Nurizon United Kingdom
T: +44 (0)1483 366 033
E: info@nurizon.co.uk